Ketchikan: Snow Removal Equipment/Sand/Urea Building FY2008 Request: \$1,000,000 Construction Reference No: 40270

AP/AL: Allocation Project Type: Construction

Category: Transportation

Location: Ketchikan **Contact:** John Torgerson

House District: Ketchikan **Contact Phone:** (907)269-0727

Estimated Project Dates: 07/01/2007 - 06/30/2012

Appropriation: Airport Improvement Program

Brief Summary and Statement of Need:

Expand or construct a new snow removal equipment, sand and chemical mixing and storage building with adequate capacity to house all of the airport's emergency response and snow removal equipment and ice control operations. This project contributes to the Department's Mission by reducing injuries, fatalities and property damage and by improving the mobility of people and goods

| Funding: | FY200 | • | , | FY2010 | FY2011 | FY2012 | FY2013 | Total |
|---|------------|------------|----------|--|---------|---------------|----------------------|-----------------|
| Fed Rcpts | \$1,000,00 | 00 | | | | | | \$1,000,000 |
| Total: | \$1,000,00 | 00 | \$0 | \$0 | \$0 | \$0 | \$0 | \$1,000,000 |
| State Match | n Required | ✓ One-Time | Project | ☐ Phased | - new | Phased - unde | rway 🔲 O | n-Going |
| 5% = Minimum State Match % Required ☐ Amendment | | | | | nent | Mental Health | Bill | |
| | | | | roject Development: Ongoing Operating: One-Time Startup: | | <u>Amo</u> | <u>unt</u> 0 0 | Staff 0 0 |
| | | | <u>-</u> | | Totals: | | 0 | 0 |

Additional Information / Prior Funding History:

FY2007 - \$1,125,000; FY2006 - \$2,875,000.

Project Description/Justification:

Ketchikan International Airport operates in a marine environment, which is corrosive to equipment. Protection of emergency response and snow removal equipment is critical to maintaining a reliable, safe and efficient airport. This project includes design and construction of a new equipment and materials building to replace the existing building that no longer meets the airport's needs. The equipment bays in the old building are too narrow and short to accommodate current equipment. The building does not provide adequate space for equipment maintenance, and it limits the effectiveness of airfield maintenance. The additional funding request is based on the most recent engineer's estimate taking into account additional building requirements, recently identified additional excavation, and general construction cost increases we have experienced with other projects.